

Platform Cable – Connects the PLATFORM to the INDICATOR through an M12 Cable.

Indicator & Platform – Components that make up your scale.

Scale Power Supply - Connects the INDICATOR to your power outlet at 5VDC. Supplies power to the Scale (Display & Platform),

PROFINET Module – PROFINET box that converts weight data from the scale to PROFINET Protocol,

PROFINET Power Supply – Powers up the PROFINET Module at 24VDC separately.